



M10x30 - 6ks
 M12x70 - 2ks (A)
 M12x19 - 3ks (C)
 M12x22 - 1ks (C)



M10 - 6ks
 M12 - 2ks (A)




PP10 - 6ks
 PP12 - 2ks (A)
 PP12 - 4ks (C)





P11 - 2ks

C




M12x19 - 3ks
 M12x22 - 1ks

DETAIL



M10x30



M10x30

M12x70

